3

С

В

Α

TOOLS REQUIRED

- 1. FLAT HEAD SCREWDRIVER OR 1/8" PUNCH (STEP 1)
- 2. IP27 TORX DRIVER (STEP 2)

4

- 3. 7/32" WRENCH (STEP 4)
- 4. LONG 3/32" HEX KEY (STEP 5)

STEP 1: USE FLAT HEAD SCREWDRIVER OR 1/8" PUNCH TO FIELD STRIP RECOIL SPRING ASSEMBLY & BOLT-CARRIER GROUP PER MANUAL

STEP 2: USE IP27 TORX DRIVER TO REMOVE TWO HANDGUARD SCREWS & SPLIT WASHER


STEP 3: SLIDE HANDGUARD ASSEMBLY FORWARD OFF OF UPPER RECIVER **ASSEMBLY**

REV.	DESCRIPTION	DATE	APPROVED
A	PRELIMINARY RELEASE	9/5/23	A. TROUT


D


С

В



2





2

REV.	DESCRIPTION	DATE	APPROVED
А	PRELIMINARY RELEASE	9/5/23	A. TROUT

STEP 4: USE 7/32" WRENCH TO LOOSEN CHARGING HANDLE ROD. PULL ROD AND SPRING OUT FROM REAR OF HANDGUARD.

STEP 5: USE LONG 3/32" HEX KEY TO REMOVE TWO #10-32 SET SCREWS FROM THE FRONT OF THE CHARGING HANDLE TROLLY

STEP 6: PULL OUT THE CHARGING HANDLE AND SLIDE THE CHARGING HANDLE TROLLY OUT OF THE HANDGUARD HEX CHANNEL

ASSEMBLY NOTES:

D

С

В

Α

- 1. REASSEMBLE IN REVERSE ORDER
- 2. CLEAN ALL THREADS WITH ACETONE OR SIMILAR SOLVENT
- 3. USE BLUE LOCTITE 243 OR SIMILAR THREAD LOCKER ON THREADS
- 4. TIGHTEN ALL THREADS TO 15-20 IN/LBS
- 5. LUBE THE EXTERIOR OF THE CHARGING HANDLE ROD & TROLLY WITH GREASE BEFORE INSTALLING HANDGUARD ON UPPER RECEIVER ASSEMBLY

3

